

PROCEEDINGS OF THE COMMISSIONER & DIRECTOR OF SCHOOL EDUCATION AND  
EX-OFFICIO PROJECT DIRECTOR, RMSA- A.P., HYDERABAD.  
Present: Smt. V. Usha Rani, I.A.S.,

Rc.No.608/RMSA/2014

Dt: 30.09.2014

Sub:- RMSA -AP- Construction of toilet blocks for boys in Secondary Schools in the State under RMSA - Certain instructions - Reg.

Read:- 1. D.O.Lr.No.27-1/2014-EE.16,dL.19.09.2014 from Addl. Secretary(SE), Govt, MHRD, Dept. of SERL, Shastri Bhavan, New Delhi.

2. School wise reports received from all the District Educational officers and Ex- Officio Project Co-Ordinators of RMSA in the State through e-mail.

\*\*\*\*\*

The attention of all the District Educational officers and Ex- Officio Project Co-Ordinators of RMSA in the State is invited to the reference 2<sup>nd</sup> read above and they are informed that as per their reports 903 Secondary Schools are not having toilet blocks for boys.


Therefore the Commissioner & Director of School Education and Ex- Officio Project Director, RMSA, AP, Hyderabad is pleased to sanction an amount of Rs.50,000/- (Rupees Fifty Thousand only) per school towards taking up of construction of toilet blocks for boys i.e., one water closet, three urinals with running water or sump (for storage of water) in those schools with the help of school building committee constituted under SMDCs of RMSA at school level as per type design (copy enclosed) after passing a resolution in the SMDC meeting to this effect and make necessary arrangements to take up the construction work at school level with the locally available material and by involving local people and philanthropists in this regard wherever they are interested, on 2<sup>nd</sup> October, 2014 under Swachh Vidyalaya Abhiyan programme duly follow the following norms and guidelines:-

1. The Head Master of the school concerned is authenticated to take up the works locally .
2. The toilet blocks works are to be taken up within the school premises and easily reachable distance to the children nearer to the existing school buildings.
3. The concerned Deputy Executive Engineer and Asst. Engineer of SSA will inspect the site selected for construction of the toilet and give marking of the construction and explain the mason, how to proceed with the work.
4. They will visit and inspect the work at the time of basement level and sort out issues if any.
5. When the work reaches roof/slab level they will inspect the work and check the re-enforcement.
6. At the time of providing water connection and fixtures the team will again inspect the work.

7. After the completion of the work, inner and outer photographs of the constructed toilet blocks should be taken and submit to this office through the District Educational officer concerned.

Hence the list of 903 Secondary schools which are not having toilet blocks for boys are herewith communicated along with the strength particulars of the schools concerned.

Encl: as above

  
Commissioner & Director of School Education  
and Ex- Officio Project Director, RMSA(FAC)

To  
All the Head Master and Chairmen, SMDCs of identified (917) Secondary Schools in the State (through District Educational Officer and Ex- Officio District Project Coordinator, RMSA concerned)  
Copy to all the District Educational Officer and Ex- Officio District Project Coordinator, RMSA in the State for information and to take necessary further follow up action in the matter.  
Copy to all the RJDSEs in the State State for information and to take necessary further follow up action in the matter.  
Copy to all the District Collectors and Chairmen, Managing Committee of RMSA in the State State for information and to take necessary further follow up action in the matter.  
SF-1  
SC-1